



# TECHNICAL BULLETIN

## PERFECT CLARITY HEADLIGHT RESTORATION (2 STEP KIT)

Meguiar's® Perfect Clarity Headlight Restoration Kit makes restoring dull, yellowed & oxidized headlights quick and easy. And Meguiar's proprietary coating prevents re-oxidation for up to a year! (Lab Tested Per ASTM G154-12a)

**Part #:** G2000

**Packaging:** Kit includes:  
1 ea - G17804 – Perfect Clarity Headlight Coating  
1 ea - G31704 – Perfect Clarity Cleaning Solution  
2 ea - Specialized cleaning pads  
3 per case

**Features:**  
• Headlights stay clear for up to a year (Lab Tested Per ASTM G154 12a)  
• Easily removes oxidation without scratching

**pH:** G17804 - N/A  
G31704 - 8

**Paintable:** G17804 - No  
G31704 - Yes

**Dilution:** RTU (Ready to use)

**Application Method:**  
G17804 – Spray on  
G31704 – Wipe on, wipe off

**Directions:** For best results, apply to a clean, cool & dry headlight in the shade. Mask around headlight before use. Immediately remove any overspray. Avoid spraying on breezy days.

**1. SHAKE PRODUCT WELL BEFORE USE.** Squeeze a quarter-sized amount of Perfect Clarity Cleaning Solution on to the cleaning pad provided. Using a back & forth motion, thoroughly clean the entire headlight surface. Reapply as needed. Wipe the headlight surface with a clean towel to check progress. The surface is properly cleaned when it has a uniform, frosted appearance across the entire headlight. Wipe clean with a damp cloth & dry completely.

**2. SHAKE PRODUCT WELL BEFORE USE.** Apply one medium wet coat of Perfect Clarity Headlight Coating to the entire headlight surface, overlapping the previous pass by 50%. Let the first coat dry 3-5 minutes. Follow with a 2nd coat to completely seal the headlight lens. The coating will be dry to touch in 3-5 minutes, and fully cured within 24 hours.

<b>Health rating:</b>	<u>G17804</u>	<u>G31704</u>
Health:	2	2
Fire:	4	0
Instability:	3	0
Specific Hazard:	None	None

**FOR ADDITIONAL SAFETY INFORMATION, CONSULT SDS KEEP OUT OF REACH OF CHILDREN**